



Tech-B11: 1990-1996 Nissan 300ZX

CAUTION: Nissan Flywheel Re-Surfacing

Clutch Kits: 06-045 & 06-046

To release system on the Nissan 300ZX does not permit for a flywheel cut of any more than .003" without causing release issues. As most normal re-surfacing exceeds this amount, the flywheel should always be replaced when installing a new clutch on this application.