



Tech-B9: Hyundai Clutch Roll Pins

Hyundai:

1986-1994 Excel

1995-5/96 Accent

Clutch Kits: 05-022, 05-023, 05-091

When installing a new clutch in the above mentioned applications it is very important to closely inspect the roll pins which hold the release bearing fork to the cross shaft. These pins often bend or break, causing release problems or complete failure. Often, the clutch will act as if the cable is stretched or is too long. It is recommended that these pins be replaced during every clutch job. O.E. numbers for these pens are:

1986 - 4/89 - Use OE Part Number 14311-06225

7/89 - 5/96 - Use OE Part Number 14311-08255